

Name Mrs. Marion Carrier

Service No. 32

Address 91 Burlington St.

Location

Lexington

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

COM. 4-6-53

Location

Date	Material	Amount	Total	Date	Amount
3/17/53	Labor	15 06		3-17-53	200 -
3/18/53	Labor	77 30		4-6-53	(17 83
		92 36			182 17
	10% overhead	9 24	101 60		
	9 1/2" - 6" Sewer Pipe @ .342		32 15		
	1-6 x 6 Y		1 28		
	Joint Compound		5 64		
	4 Hr. Town Shovel @ 5.00		20 00		
	2 Hr. Trucking		1 50		
	Patching 20 x 3		20 00		
			182 17		
	Labor				

