

Name J. V. MacDonald

Service No. 177

Address 93 Burlington St.

Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Recovery~~ — New Service

COM. 11-23-53

Location

Date	Material	Amount	Total	Date	Amount
10/14/53	Labor	54 17		10-1-53	Deposited 175 00
	10% overhead	5 42	59 59	11-23-53	Refunded (3428)
	54'-6" Sewer Pipe @ .3036		16 39		140 72
	Joint Compound		3 24		
	8 Hr. Littlefield Shovel @7.50		60 00		
	2 Hr. Trucking		1 50		
			140 72		
	Labor			663-74	Solids

