

Name Donald Sparrow

Service No. 204

Address 97 Burlington Street

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Location *Conn 12-12-60*

Date	Material	Amount	Total	Date	Amount
11-14-60	Labor	74.96		11-6-60	250.00
11-15-60	Labor	29.43		1-18-61	7.17
		104.39			257.17
	10% O.H.	10.44	114.83		
	48' 6" Transite pipe @.78		37.44		
	1 6" 90° Transite Elbow		5.40		
	1 11 1/4" Transite Bend		5.10		
	1 6" Duplex Adapter		1.90		
	3 hrs. Town Shovel @6.50		19.50		
	5 hrs. Trucking @3.00		15.00		
	2 hrs. Allis Chalmers @3.00		6.00		
	1 hr. Pumping @1.00		1.00		
	1 hr. Rogers Trailer @3.00		3.00		
	12 X 12 Patch		48.00		
			257.17		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching sewer service details.

Connection made in Street. Work completed

Remarks:
.....
.....