



Address	Map and Lot	Permit Number	Contractor Name	Inspector
18 Calvin St	83-57	7076	Bradley Landscaping	mweis
Date	Material	Depth of Cover	Amount	
2/1/2018	6" PVC Pipe - SDR 35		45 ft	
	6" Cleanout		1	
	6" 22 deg bend		0	
	6x6 fernco		1-connect to existing	
Type of work completed				
Renew 6" PVC sewer service connected near ROW				