

Name George S. Lfridge

Service No.

Address 10 Carley Road

Lexington, Miss.

Location 10 Carley Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~New Service~~

Com. 8-16-48

Location

Date	Material	Amount	Total	Date	Amount
------	----------	--------	-------	------	--------

June 28, '48

Jul. 13, '48

Labor	105 81	105 81
10% Overhead		10 58
58' - 6" Sewer Pipe @ .26		15 08
1 - 6" Elbow		1 50
Joint Compound		3 48
Compressor 9 hrs. @ 1.75		15 75
Littlefield Shovel 2 hrs.		14 00
Dynamite 9 lbs. @ .21		1 89
Caps 24 @ .11		2 64
Trucking 2 hrs. @ .75		1 50
		<u>172 23</u>

Labor

May 24 '48

Mar 5 '49

Mar 8 '49

9-23-03

10-6-03

Hydrant

Paint

Paint

Roots and debris  
53' - Respond  
+ MEASURE  
Roots + Debris About  
36' to 40' Feet Out-Respond

25 00

45 00

3 05

99 15

172 23

