

Name Todd Realty Trust

Service No.

Address 6 Carol Lane

Lot #3

Location

Kind of Pipe

Size

Size of Main

Repair—Renewal—New Service

DeFlice #1285
Lucente # 994

Location

Date

Material

Amount

Total

Date

Amount

~~1968~~ 35' 6" Transite Pipe

3-25-69 40' 6" Transite Pipe

13' 4" Cast Iron

1968

35' 6" Transite

1 6" X 8" Wye

