

Name John Yosgandes

Service No. 173

Address 11 Carville Ave.

Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair - Renewal~~ - New Service

Committed 12-8-52

Location

Date	Material	Amount	Total	Date	Amount
11/14/52	Labor	30 12		11-10-52	150 00
11/17/52	Labor	38 37		12-8-52	19 20
	10% Overhead	6 85	75 34		130 80
	40' - 6" sewer pipe @.342		13 68		
	1 - 6" elbow		1 88		
	joint compound		2 40		
	3 hrs. town shovel @.5		15 00		
	2 hrs. trucking @.75		1 50		
	patching 21 X 3		21 00		
			130 80		
	Labor				

