

Name George Larson

Service No. 38

Address 27 Carville Avenue

Location 27 Carville Avenue

Kind of Pipe

Size

Size of Main

Repair ~~Renewal~~ - New Service

Com. 8x22x49x

Location

Date	Material	Amount		Total		Date	Amount
		10-10-49	10-10-49	10-10-49	10-10-49		
June 9, '49	Labor	33	30	33	30	June 1, '49 Deposited	125 00
June 10, '49	Labor	33	85	33	85	Oct 13 '49 Collected	6 96
	10% Overhead			6	72		118 04
	42' - 6" Sewer Pipe @.265			11	13		
	1 - 6" Elbow			1	52		
	Joint Compound			2	52		
	Littlefield Shovel 2 1/2 hrs. @7.00			17	50		
	Trucking 2 hrs. @.75			1	50		
	Patching 10 x 3			10	00		
				118	04		
	Labor						

