

Name Donald K. Irwin

Service No. 53

Address 43 Carville Avenue

Lexington, Mass.

Location 43 Carville Avenue

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Com. 11-14-49

Location

Date	Material	Amount	Total	Date	Amount
Jul. 27, '49	Labor	49 60	49 60	July 18 '49	100 00
	10% Overhead		4 96	Nov 17 '49	2 39
	54' - 6" Sewer Pipe @.265		14 31		97 61
	Joint Compound		3 24		
	Littlefield Shovel 2 hrs. @ 7.00		14 00		
	Trucking 2 hrs. @.75		1 50		
	Patching 10 x 3		10 00		
			97 61		
	Labor				

