Name Service No. **3**8 F. W. Spearin Address 23 Cedar Street Location Size of Main Kind of Pipe Size Location Comm 7-6-59 XRepairxxRenxwatxxNew Service Date Material Total **Amount Amount** Date Deposit 5-12-59 Labor 63.07 4-117-59 8-7-54 Labor **33.**83 5-13-59 96.30 10% O.H. 9.63 105 93 47 6" Transite pipe @.70 32.90 6" Clay Elbow 1188 hrs. Pippin Shovel @4.50 22150 hrs. Trucking @.75 1150 hrs. Compressor 3.00 6100 12 x 3 Patch 12100 182 71 Labor H.B.M.18501

TOWN OF LEXINGTON—DEPT. OF PUBLIC WORKS SEWER DIVISION

reet and hereb wers, as now n't of estima n't Paid \$	or a	it a 5	an y	fu	tur 	e ti																-	th	ie	COI	nsti	ruc	tio	n a	anc	d u	ise (of 1	Part	icula
		_	 ,				- - -				_			<u> </u>	_==			_	===:	•		··-		•••		· ·					· · ·	· · · · ·		c)wne
												Sk	etc	h	of	Se	rvi	ice	He	ere															
							I														I	Ţ								Į					
			_	4	4	_	1	<u> </u>	1	<u>l</u> _	_]	1	<u> </u>]_	<u> </u>	<u> </u>	<u>ļ </u>		_	\downarrow	4	ļ_	Ļ		<u> </u>			4	_	_				
	-	_				+	+	+-	}_	 	 	 _	<u> </u> _	1_	+	+	<u> </u>	<u> </u>			+	- 	+	1	<u> </u>	<u> </u>	<u></u>		+	{{1}}	4				
		_		-+	+	╬		 -	<u> </u>	}	<u> </u>	 	1-	 	╀	<u> </u>	<u> </u>	 		-	+	+	+	+-	+-	<u> </u> 	-		+	-{	{				
					÷	- }-	÷	╁	} -	1	} -	1_	╁╴	╁╴	╁╴	╫	<u> </u>	}	<u> </u>		-¦-	÷	╁	+	'	<u> </u>	_	<u> </u>	- 	{	{				
				十	\dagger	Ť	†-	†	\vdash	Ť	 	-	Ì-	╁╴	Ť	ì	Ì	Ì	<u> </u>		寸	十	十	亡	<u> </u>	-			T	ij	\neg				
					Ì	Ì.	Ī				<u> </u>	Ī	Ì	Ť_	İ							Ī									\Box .				
					Ţ	\perp	Ţ	1_	1_			1	<u> </u>			匚						<u> </u>	上	Ĺ	<u> </u>				[_					
		_ !	_	\downarrow	4		<u> </u>	<u> </u>	<u> </u>	1_	<u> </u>	<u> </u>	Ļ		1	Ļ	<u> </u>	1		1	_ }	1	ᆜ_	<u> </u>	<u> </u>			<u> </u>	_	_ļ					
			_	+	\perp	1	1	<u> </u>	<u> </u>			1_	_	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<u> </u>		1	-	+	+	<u> </u>	1	_]			4					
			t	- T		T		1	1	1	1	1	1	1	1	1	1	1	i '	- }	- 1	- }	1	}	1	1	1 1	i. 1	- 1	- 1	ĺ				