

Name Buster Lofton

Service No. 3

Address 28-30 Cedar Street

Location

Kind of Pipe

Size

Size of Main

~~Repair~~—Renewal—~~New Service~~ W.O. #3123

Location *Comm 7-28-75*

Date	Material	Amount	Total	Date	Amount
2-28-75	Labor	71.97		<i>2-27-75</i>	<i>Deposit 150.00</i>
	10 % O.H.	<u>7.20</u>	\$79.17	<i>7-28-75</i>	<i>Ret'nd 32.51</i>
15'	6" Transite Pipe	@1.27	19.05		<i>117.49</i>
1	6" Coupling		2.41		Outside (non-charge)
1	Donut		3.05	2-2-75	Labor 11.56
6	Bricks	@.09	.54	4'	6" Transite Pipe @1.27 5.08
$\frac{1}{2}$	Bag Cement		.77	1	Hr. Trucking 3.00
2	Hrs. Trucking		3.00	1	Hr. Pick up 1.50
1	Hr. Backhoe		<u>6.50</u>	1	Hr. Loader 4.00
			\$117.49	1	Hr. Compressor 5.00
				1	Patch 35' x 1' x 1' 22.80
					\$ 52.94

DATE \_\_\_\_\_

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large grid of graph paper, consisting of approximately 20 columns and 25 rows of small squares, intended for sketching service details.

Connection made in ..... Street. Work completed .....

Remarks: *Original Service* ..... *12-22-31* .....

.....  
.....