

Name John Kiley

Service No. 133

Address 10 Chase Avenue

Lexington, Mass.

Location 10 Chase Avenue

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ - New Service

Com. 2-19-51

Location

Date	Material	Amount	Total	Date	Amount
1-10-51	Labor	23 33	23 33	Dec 6 '50	125 00
	10% Overhead		2 33		1 72
	36' - 6" Sewer Pipe @.34		12 38		114 58
	1 - 6" Elbow		1 88		
	Joint Compound		2 16	Repair made 5-11-98 possibly silt left	
	Littlefield Shovel 7 hrs. @.70		49 00	in pipe	
	Trucking 2 hrs. @.75		1 50		
	Patching 22 x 3		22 00		
			114 58		
	Labor				
				5-11-98 <del>Station</del> RESPOND.	

