

Name Francis Camposi

Service No. 87

Address 36 Chase Avenue

Location Lexington, Mass.

Kind of Pipe

Size

Size of Main

~~Repair~~ New Service *Com. 10-1-51*

Location

Date	Material	Amount	Total	Date	Amount
8-29-51	Labor	41 84	41 84	Aug 3 51	125 00
	10% Overhead		4 18	10-1-51	26 15
	50'-6" Sewer Pipe		17 10		1 35
	1-6" Elbow		1 88		97 50
	Joint Compound		3 00		
	4 Hrs. Littlefield Shovel		28 00		
	2 Hrs. Trucking		1 50		
			97 50		
	Labor				

