

Name Robert Levine

Service No. 58

Address 1 Compton Circle

Location 1 Compton Circle

Kind of Pipe

Size

Size of Main

~~Repair/Renewal~~ New Service Valeri #3858

Location FEB 27 1984

Date	Material	Amount	Total	Date	Amount
<del>10/-/63</del>	<del>26.3' 6" A.C.</del>			11-11-83	Deposit
	installed by contractor				157 80
	@ 6.00 per foot	157 80		10- - 63	
	BILL WHEN CONNECTED			263'	6" A.C.
11/22/83	68' 6" PVC				
	2 22° Bend				
	4" x 6" Donut				

