

Name William L. Hench

Service No.

Address 23 Coolidge Avenue

Location

Kind of Pipe

Size

Size of Main

Repair—~~REPAIR ON NEW PIPING~~ W.O. #7375

Location

Date	Material	Amount	Total	Date	Amount
9/9/68	Labor 124.93				
10/1/68	Labor <u>22.54</u>	147 47			
	10% O.H.	<u>14 75</u>	162 22		
12'	6" Transite @ .88		10 56		
1	22 $\frac{1}{2}$ " ^o Elbow		2 35		
1	11 $\frac{1}{4}$ " ^o Sweep		4 09		
1	Bag Cement		1 55		
$\frac{1}{8}$	Ton Loam		88		
1	Lb. Seed		1 10		
1 $\frac{1}{2}$	Ton Hot top @ 5.80		8 70		
6 $\frac{1}{2}$	Hrs. Trucking @ 3.00		19 50		
5	Hrs. Shovel @ 6.50		32 50		
1	Hr. Loader		4 00		
1	Hr. Compressor		5 00		
$\frac{1}{2}$	Hr. Trailer @ 1.50		75		
$\frac{1}{2}$	Hr. Roller @ 3.00		<u>1 50</u>		
			\$ 254 70		

