

Name Paul E. Martin

Service No. 150

Address 15 Crescent Hill Road Avenue

Location

Comm. 11-18-57

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ — New Service

Installed by contractor

Location

| Date | Material | Amount | Total | Date | Amount |
|----------|-------------------------------|--------|--------|----------|------------------|
| 10/27/57 | Labor | 47 27 | | 7-10-57 | Deposit |
| | 10% overhead | 4 73 | | 11-18 57 | Refused |
| | | | 52 00 | | NON CHARGE |
| | 36' 6" Transite @ .70 | | 25 20 | | Labor |
| | 1 1/4x6" clay elbow | | 1 88 | | 10% overhead |
| | 3 hrs. Northwest shovel @6.50 | | 19 50 | | Health welfare |
| | 3 hrs. trucking @.75 | | 2 25 | | Hough |
| | 2 hrs. Hough @ 3.00 | | 6 00 | | Northwest shovel |
| | 1 hr pump @ 1.00 | | 1 00 | | Trucking |
| | 1 hr. compressor | | 3 00 | | Pump |
| | 93 x 3 patch | | 13 00 | | |
| | | | 123 83 | | |
| | Labor | | | | |

