

Name

Service No.

Address 55 Cummings Avenue

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service


Location

Date	Material	Amount		Total		Date	Amount	
9-26-59	Labor	70	90					
	10% O. H.	7	09	77	99			
	22' 6" Transite pipe @.70			15	40			
	1 6" 1/8 Clay Bend			1	24			
	3 Hrs. Shovel @6.50			19	50			
	1 Hr. Trucking				75			
				114	88			

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:

.....

.....