

Name Antonio Zusa

Service No. 143

Address 8 Cummings Avenue

Location

Kind of Pipe

Size

Size of Main

~~Repair Renewal~~ - New Service

COM. 12-31-54

Location

| Date | Material | Amount | Total | Date | Amount |
|----------|---------------------------|--------|--------|----------|-------------------|
| 12/11/54 | Labor | | 78 55 | 11-17-54 | Deposited 100 00 |
| | 10% overhead | | 7 86 | 12-31-54 | Paid g/c 7 01 |
| | 50' - 6" sewer pipe @ .32 | | 16 00 | 3-21-55 | Paid (11 78 |
| | 1 - 6" Elbow | | 1 88 | | 11 8 79 |
| | Joint compound | | 3 00 | | |
| | 2 hrs. Town shovel @ 5.00 | | 10 00 | | |
| | 2 hrs. trucking @ .75 | | 1 50 | | |
| | | | 118 79 | | |
| | | | | | bill sent 11-1-55 |
| | Labor | | | | |

