

Name Donald Jenkins

Service No. 31

Address 7 Dane Road

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Location


Comm 6-19-61

Date	Material	Amount	Total	Date	Amount
4-14.-61	Labor 24.22			4-13-61	250.00
4-28-61	" 62.03	86.25		6-19-61	43.13
	10% O.H.	8.63	94.88		206.87
	71' 6" Transite Pipe @.78		55.38		
	1 22 ¹ / ₂ ° Transite Bend		6.21		
	1 90° Transite Elbow		5.40		
	6 hrs. Pippin Shovel @5.00		30.00		
	3 hrs. Trucking @3.00		9.00		
	6 x 3 Patch		6.00		
			206.87		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:
.....
.....