

Name **Harold S. Franklin**

Service No. **161**

Address **Dee Road**

Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ **New Service**

Committed 12-8-52

Location

Date	Material	Amount	Total	Date	Amount
11/12/52	Labor	48 73		10-27-52 Deposited	150 00
	10% Overhead	4 87	53 60	12-8-52 Refunded	28 19
	54' - 6" sewer pipe @ .342		18 47		NON CHARGE
	Joint compound		3 24	11/12/52 Labor	14 62
	4 hrs. Littlefield shovel @ .7		28 00	11' - 8" sewer pipe @ .62	6 82
	2 hrs. trucking @ .75		1 50	1 - 8X6 Y	2 20
	patching 17 X 3		17 00	joint compound	60
			121 81	2 hrs. Littlefield shovel @ .7	14 00
				1 hr. trucking @ .75	75
				patching 11 X 3	11 00
					49 99
	Labor				

