

Name Clarence E. Delp

Service No. 79

Address 18 Dexter Road  
Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ — New Service COM. 9/8/52

Location

Date	Material	Amount	Total	Date	Amount
7/21/52	Labor	32 34		5-23-52	Deposited 125 00
	10% overhead	3 23	35 57	9-10-52	Refunded (2) 25
	48' - 6" sewer pipe @ .342		16 42		127 25
	1 - 6" elbow		1 88		
	joint compound		2 88		
	7 hrs. Littlefield shovel		49 00		
	2 hrs. trucking		1 50		
	patching 15 x 3		15 00		
			122 25		
	<b>Labor</b>				

