

Name James I. Grant

Service No. 123

Address 29 Dexter Road

Lexington, Mass.

Location 29 Dexter Road

Kind of Pipe

Size

Size of Main

~~Repair or Renewal~~ New Service

Location

Date		Material	Amount	Total	Date	Amount
Nov. 22, '48		Labor	32 13	32 13	Oct. 30 1948	100 00
		10% Overhead		3 21	Dec 31 48	16 02
		52'-6" Sewer Pipe @ .26		13 52		83 98
		1-6" Elbow		1 50		
		Joint Compound		3 12		
		2 hrs. Littlefield Shovel		14 00		
		2 hrs. Trucking		1 50		
		Patching 15 x 3		15 00		
				83 98		
		Labor				

