

Name Calvert Cox

Service No. 62

Address 33 Dexter Road
Lexington, Miss.

Location 33 Dexter Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~XXXX~~ New Service

Com. 11-14-49

Location

Date	Material	Amount	Total	Date	Amount
Aug. 5, '49	Labor	41 85	41 85	July 20 '49	115 00
	10% Overhead		4 19	Nov 19 '49	11 51
	46' - 6" Sewer Pipe @.265		12 19		103 49
	Joint Compound		2 76		
	Littlefield Shovel 4 hrs. @7.00		28 00		
	Trucking 2 hrs. @ .75		1 50		
	Patching 13 x 3		13 00		
4-19-77	Renewal		103 49		
	30' 6" Transite				
	1 4" DONUT				
	Labor				

