

Name **Leeland Construction Company**

Service No. **41**

Address **61 Dexter Road**

Lexington

Location

61 Dexter Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ **New Service**

Comm. 11-6-50

Location

Date		Material	Amount		Total		Date		Amount	
July 7	'50	Labor	25	22			<i>June 21 '50</i>	<i>Depleted</i>	125	00
		10% Overhead	2	52	27	74			32	44
		48' - 6" Sewer Pipe @ 28¢			13	44			92	56
		Joint Compound			2	88				
		4 hrs. Littlefield Shovel			28	00				
		2 hrs. Trucking @ 75¢			11	50				
		Patching 19' x 3'			19	00				
					92	56				
		Labor								

