

Name A. R. Miller

Service No. 45

Address 68 Dexter Road

Lexington

Location 68 Dexter Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~DK~~ - New Service

Com. 11-6-50

Location

Date		Material	Amount.		Total		Date		Amount
July 18	'50	Labor	30	80			July 6 '50	125 00	
		10% Overhead	3	08	33	88	<i>Depainted</i>	10 24	
		48' - 6" Sewer Pipe @ 28¢			13	44		114 76	
		1 - 6" Elbow			1	56			
		Joint Compound			2	88			
		4½ hrs. Littlefield Shovel			31	50			
		2 hrs. Trucking			1	50			
		Patching 30 x 3			30	00			
					114	76	4-23-64	4 03	
		Labor							

