

Name **Helene M. Sutton**

Service No. 203 (1953)

Address **11 Donald Street**

Location

Kind of Pipe

Size

Size of Main

~~Repair~~

~~Service~~ — **New Service**

Com. 2-23-54

Location

Date	Material	Amount	Total	Date	Amount	
1/10/54	Labor	83 20		11-30-53	<i>Deposited</i>	125 00
	10% overhead	8 32	91 52	2-23-53	<i>Refunded</i>	(28
	46' - 6" sewer pipe @ .3087		14 20			124 72
	1 - 6" 1/8 bend		1 24			
	joint compound		2 76			
	3 hrs. town shovel @ 5.00		15 00			
			124 72			
	Labor					

