

Name Alfred P. Williams

Service No. 136

Address 3 Donald St.

Lexington

Location

Kind of Pipe

COM. 9-14-53

Size

Size of Main

~~Repair~~ ~~Renew~~ ~~Work~~ — New Service

Location

Date	Material	Amount	Total	Date	Amount
8/18/53	Labor	27 75		7-16-53	Deposited 12.50
	10% overhead	2 78	30 53	9-14-53	Refunded (38 74)
	1/6" - 6" Sewer Pipe @ .3036		13 97		86 26
	Joint Compound		2 76		
	5 Hr. Littlefield Shovel @ 7.50		37 50		
	2 Hr. Trucking		1 50		
			86 26		
	Labor				

