

Name Dr. Donald Taylor

Service No. 90

Address 38 Downing Rd.

Location

Lexington

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

COM. 7-13-53

Location

Date	Material	Amount	Total	Date		Amount
6/8/53	Labor	25 00		5-18-53	Deposited	125 00
	10% overhead	2 50	27 50	7-13-53	Refunded	(27 50)
	40'-5" Transite Pipe @.55		22 00			97 50
	5 Hr. Littlefield Shovel @7.50		37 50			
	2 Hr. Trucking		1 50			
	Patching 9 x 3		9 00			
			97 50			
	Labor					

