

Name <sup>B.</sup> B. W. Rogers

Service No. 114

Address 38 Eaton Rd.

Lexington

Location

Kind of Pipe

Size

Size of Main

~~REPLACEMENT~~ New Service

COM. 11-3-52

Location

Date	Material	Amount	Total	Date	Amount
9/24/52	Labor	38 23		8-7-52	Deposited 175 -
9/25/52	Labor	34 96		11-3-52	Paid a/c 3 84
9/26/52	Labor	20 58		1-11-52	Abated 16 63
	10% Overhead	9 38	103 15		
	52' - 6" sewer pipe @ .342		17 78		
	joint compound		3 12		
	8 hr. Littlefield shovel		56 00		
	5 lbs. dynamite @ .24		1 20		
	5 exploders @ .1435		72		
	2 hr. trucking @ .75		1 50		
	patching 12 X 3		12 00		
			195 47		
	Labor				

