

Name Daniel Branton

Service No. 113

Address 14 Eliot Road

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~New Service~~ W.O. #6262

Location MAY 22 1978


Date	Material	Amount	Total	Date	Amount
4/26/78	Labor	271.45		11-25-77	135.00
	10% O.H.	27.15	298.60	5-26-78	452.39
	80' 6" Transite @1.50		120.00		576.39
	1 12" Nipple		2.50		
	1 30° Bend		9.80	4/26-27 & 6/9/78	
	1 4" Donut		3.55	2	10' of 6" Transipe pipe
	9 6" Couplings @2.16		19.44	1	30° Transite Bend
	10 yds. Loam @5.44		54.40	1	6 x 10 Saddle
	2 Bags Fertilizer @4.00		8.00	2	6" Couplings
	2 Bags Lime @1.00		2.00	2	yds. Loam
	4 hrs. Trucking @3.00		12.00		Patch 13 x 7 Street
	4 hrs. Backhoe @6.50		26.00		Patch 9 x 5 Sidewalk
	5 hrs. Dozer @4.00		20.00		Trucking etc.
			576.29	5-5-95	Blockage 140' - plumber
					Respond to measure
				3-5-98	Roots 72' out Homeowner problem

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here



Connection made in Street. Work completed

Remarks:
.....
.....