

Name Benjamin Franklin Homes

Service No. 33

Address 357 Emerson Road

Lot 30 Sta.10+69

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~New Service~~

Richard Stevens Permit #272

Location MAY 17 1965

Date	Material	Amount	Total	Date	Amount
<del>9-11-62</del>	Labor	38.94		<del>4-30-65</del>	<del>87.65</del>
	10% O.H.	3.89	42.83		
	<del>39' 6" Transite pipe @.82</del>		<del>31.98</del>		
	<del>4 6 x 12 Service Saddle</del>		<del>5.75</del>	9-11-62	
	<del>1 11 1/4" Transite Bend</del>		<del>4.09</del>	39' 6" Transite	
	1 hr. Trucking @3.00		3.00	1 6" X 12" Service Saddle	
	BILL WHEN CONNECTED		87.65	1 6"-11 1/4" Bend	
5-4-65	90' 6" Transite pipe				

