

Name Benjamin Franklin Homes

Service No. 86

Address 360 Emerson Road

Lot # 39

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ — New Service W.O. #7369

Location ? 12-10-62

Date	Material	Amount	Total	Date	Amount
6-27-62	Labor	98.19		6-27-62	175.00
6-28-62	"	35.01	133.20	12-10-62	23.74
	10% O.H.	13.32	146.52	12-21-62	86.47
122	6" Transite pipe @82		100.04		284.41
9	9' on 3/4" Stone @1.50		13.50		
1	6X10 Transite Nipple		.91		
1	11 1/4" Transite Elbow		2.35		
16	X 6 Tee Transite		4.09		
4	Hrs. Trucking @3.00		12.00		
5	Hrs. Pumping @1.00		5.00		
			<u>284.41</u>		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 25 rows high, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....