

Name **Dean R. Burleigh**

Service No. 60

Address **14 Fair Oaks Drive**

Lexington

Location

Kind of Pipe

Size

Size of Main

~~Repair Renewal~~ **New Service**

COM. 6-16-52

Location

Date	Material	Amount	Total	Date	Amount
12/52	Labor	33 79		4-25-52 Deposited	50 00
	10% overhead	3 38	37 17	6-10-52 Refunded	31
	24' - 6" sewer pipe @ .342		8 20		49 69
	1 - 6" 1/8 bend		1.38		
	joint compound		1.44		
	2 hrs. trucking		1.50		
			49 69		
	Labor				

