

Name **Herbert McLauthlin**

Service No. **75**

Address **15 Fair Oaks Drive**

**Lexington**

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ **New Service**

COM. 7-28-52

Location

Date	Material	Amount	Total	Date	Amount
6/23/52	Labor	83 25		5-19-52	Deposited 125 -
	10% overhead	8 33	91 58	7-28-52	Refunded ( 6 56
	60' - 6" sewer pipe @ .342		20 52		118 44
	1 - 6" 1/8 bend		1 24		
	joint compound		3 60		
	2 hrs. trucking		1 50		
			<u>118 44</u>		
	Labor				

