

Name **Henry J. Moulton, Jr.**

Service No. **66**

Address **20 Fairbanks Road**

Location *Comm. 10-29-56*

Kind of Pipe

Size

Size of Main

~~Repair/Replacement~~ **New Service**

Location

Date	Material	Amount	Total	Date	Amount
7/2/56	Labor	31 20		6-6-56	<i>Deposit</i> 100 00
	10% Overhead	3 12	34 32	10-29-56	<i>Refund</i> 12 68
	100' 6" Sewer pipe @.455		45 50		87 32
	Joint Compound		6 00		
	2 hrs. trucking @.75		1 50		
			<u>87 32</u>		
	Labor				

