

Name

Service No.

Address 36 Fairbanks Road

Location

Kind of Pipe

Size

Size of Main

~~Repair~~—Renewal—~~New Service~~ W.O.#5555

NON CHARGE

Location

Date	Material	Amount	Total	Date	Amount
10-6-67	Labor	166.56			
10-7-67	"	179.98			
10-9-67	"	46.46			
10-10-67	"	22.52			
10-27-67	"	21.09			
10-27-67	"	21.26	457.87		
	58' 6" Transite pipe @.88		51.04		
	1 11 $\frac{1}{4}$ " ^o Transite Elbow		2.35		
	1 22 $\frac{1}{2}$ " ^o Transite Elbow		4.09		
	1 Adapter		2.76		
	$\frac{1}{2}$ ton Cold Patch @5.00		2.75		
	2 " Loam		7.00		
	1 lb Seed		1.10	$\frac{1}{2}$ hr. Welder	1.50
	5 lbs Fertilizer		4.00	$\frac{1}{2}$ hr. Trailer	2.00
	4 ton Hot Top		23.20	$\frac{1}{2}$ hr. Compressor	2.50
	11 $\frac{1}{2}$ hrs. Trucking @3.00		34.50		
	15 hrs. Shovel		97.50		
					739.95

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 25 rows high, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....

