

Name Donald B. Banks

Service No. 221

Address 59 Farmcrest Road

Location

Kind of Pipe

Size

Size of Main

~~REPAIR~~ ~~RENEW~~ New Service

Location *Comm 5-4-59*

Date	Material	Amount	Total	Date	Amount
3-19-59	Labor	80 07		<i>4-28-59</i>	<i>150 00</i>
3-20-59	"	56 65		<i>5-14-59</i>	<i>137 27</i>
		136 72			<i>287 27</i>
	10% O.H.	13 67	150 39		
	60' 6" Transite Pipe @.70		42 00		
	1 6" Clay Elbow		1 88		
	9 Hrs. Town Shovel @6.50		42 00		
	2 Hrs. Trucking @.75		1 50		
	3 Hrs. Compressor @3.00		9 00		
	2 1/2 x 3 Patch		24 00		
			287 27		
	Labor				

