

Name Emma M. Locke

Service No. 87

Address 64 Farmcrest Avenue

Lexington

Location 64 Farmcrest Avenue

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ **New Service**

Comm 11-6-50

Location

Date		Material	Amount		Total		Date		Amount	
Oct. 2	'50	Labor	29	45			<i>Sept. 25 '50</i>	<i>Deposited</i>	100	—
" 3	"	"	40	30			<i>Nov 20 '50</i>	<i>Paid</i>	2	75
		10% Overhead	6	98	76	73			107	75
		36' - 6" Sewer Pipe			9	36				
		Joint Compound			2	16				
		2 hrs. Brox Shovel			18	00				
		2 hrs. Trucking			1	50				
					107	75				
		Labor								

