

Name Randall W. Richards

Service No. 109

Address 67 Farmcrest Avenue

Lexington, Mass.

Location 67 Farmcrest Avenue

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ **New Service**

Com. 2-19-51

Location

Date	Material	Amount	Total	Date	Amount
1-19-51	Labor	21 60	21 60	Oct 13 '50	1000
	10% Overhead		2 16		32 23
	82' - 6" Sewer Pipe @.34		28 21		117 07
	1 - 6" - Y		1 16		
	1 - 6" - 1/8 Bend		1 52		
	Joint Compound		4 92		
	Littlefield Shovel 8 hrs. @7.00		56 00		
	Truckling 2 hrs. @.75		1 50		
			117 07		
	Labor				

