

Name Robert May

Service No. 112

Address 16 Fletcher Ave.

Location

Kind of Pipe

Size

Size of Main

~~REPAIR~~—Renewal—~~REPAIR SERVICE~~

Location

FEB 13 1978

Date	Material	Amount	Total	Date	Amount	
11/29/77	Labor	78 60		11-25-77	Deposit	300 00
	10% O.H.	7 86	86 46	2-13-77	Refund	46 54
	20' 6" Transite @ 1.50		30 00			153 46
	1 4" Donut		3 55		OUTSIDE	
	2 Yds. Loam @ 4.50		9 00	11-28-77	Labor	
	5 lbs. Seed @ .39		1 95	4/5/78	Labor	
	1 Hr. Trucking		3 00		2 6" x 10' Transite pipe	
	3 Hr. Backhoe @ 6.50		19 50		1 6" x 8" Saddle	
			153 46		1 11 1/4" Bend	
					1 Ton Cold Patch	
					Patch 8 x 16	
					Patch 8 x 7	
					4 hrs. Trucking	
					1/2 hr. Roller	
					2 1/2 hrs. Case	
					1/2 hr. Compressor & Loader	

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here

Connection made in Street. Work completed

Remarks:

