

Name Alice D. Stringos

Service No. 114

Address 50 Fletcher Avenue

Location Comm. 11-18-57

Kind of Pipe

Size

Size of Main

Repair ~~Renewal~~ New Service

Location

Date	Material	Amount	Total	Date		Amount
3-22-57	Labor	50.20				
	10 % O.H.	5.02	55.22	8-12-57	Deposit	\$ 200.00
	89' 6" Transite pipe @.70		62.30	11-18-57	Refund	48.41
	1 6" Elbow		1.88		NON CHARGE	151.59
	1 Cesspool Cover & Frame		10.50	8-21-57	Labor	32.88
	100 Sewer Blocks @.38 per 1000		3.80			
	2 bags Cement @ 1.32		2.64			
	2 hrs Town Shovel @ 6.50		13.00			
	3 hrs. Trucking @.75		2.25			
			151.59			
	Labor					
					GOS OUT TO HAYES LANE	

