

Name Ralph J. Frissore

Service No. 118

Address 9 Fletcher Avenue

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ — New Service

com. 8-15-55

Location

Date	Material	Amount	Total	Date	Amount
6/22/55	Labor	28 28		6-14-55	Deposited 150 00
	10% overhead	2 83	31 11	6-15-55	Refunded 32 29
	4 1/2' - 6" sewer pipe @ .32		14 08		117 71
	1 - 6" elbow		1 88		
	joint compound		2 64		
	5 2/3 hrs. Littlefield shovel	@ 7.50	42.50		
	2 hrs. trucking @ .75		1 50		
	patching 24 x 3		24 00		
			117 71		
	Labor				

