

Name Marek Grynberg

Service No. 77

Address 18 Flintlock Road

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ Renewal ~~NEW SEWER~~ W.O. #33

Location

NOV 13 1978

Date	Material	Amount	Total	Date	Amount
10-23-78	Labor	83.03		10-20-78	400.00
10-24-78	"	28.98			105.24
10-26-78	"	38.10	150.11		294.76
	10% O.H.	15.01	165.12		
	40' 6" Transite Pipe @1.50		60.00	10-15, 23, 24 & 26-78	
	1 22 1/2° Bend		10.50	1	6" x 10' Transite pipe
	1 4" Donut		3.05	1	6" x 5' Transite nipple
	6 yds. Loam @5.44		32.64	12	White Brick
	5 lbs. Seed @.74		3.70	1	bag Cement
	1/2 bag Lime		.50	6	yds. Gravel
	1/2 bag Fert.		2.00	4	yds. Loam
	2 1/2 hrs. Trucking @3.00		7.50	2	lbs. Seed
	1 1/2 hrs. Backhoe @6.50		9.75	4 1/2	hrs. Trucking
			294.76	1 1/2	hrs. Compressor
				2	hrs. Town Shovel

Deposit
Retaind

OUTSIDE W.O. #40

Patch 15' x 6'
10-17, 20-78

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 25 rows high, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....