

Name Ernest Cutter

Service No. 76

Address 127 Follen Road

Lexington, Mass.

Location 127 Follen Road

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ ~~XL~~ New Service

Com. 12-19-49

Location

Date	Material	Amount	Total	Date	Amount
ov. 18, '49	Labor	46 47		Nov. 19 '49	25 00
ov. 19, '49	Labor	38 40	84 87	June '50	45 11
	10% Overhead		8 49		120 11
	50' - 6" Sewer Pipe @ .265		13 25		
	Joint Compound		3 00		
	Brox Shovel 1 hr. @ 9.00		9 00		
	Trucking 2 hrs. @ .75		1 50		
			120 11		
	<b>Labor</b>				

