

Name Reginald Wood

Service No. 111

Address 48 Fremont Street

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ New Service

Location Comm 11-13-61

Date	Material	Amount	Total	Date	Amount
9/7/61	Labor	68 64		8-28-61	200 00
9/4/61	"	11 91		11 13 61	13 63
		80 55			186 37
	10% O.H.	8 06	88 61		
	62' 6" Transite pipe @ .78		48 36		
	1 6" 90° Transite Elbow		5 40		
	7 Hrs. Pippin Shovel @ 5.00		35 00		
	3 Hrs. Trucking @ 3.00		9 00		
			186.37		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large rectangular grid of graph paper, consisting of approximately 20 columns and 25 rows of small squares, intended for sketching service details.

Connection made in Street. Work completed

Remarks:

.....

.....