

Name Leeland Construction Company

Service No. 143

Address 69 Fremont St.,

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ — New Service

Location *Comm 12-4-61*

Date	Material	Amount	Total	Date	Amount
10/19/61	Labor	73 27		10-9-61	200 00
10/20/61	"	24 03		12-4-61	4 01
		97 30			195 99
	10% O.H.	9 73	107 03		
	61'6" Transite Pipe @ .78		47 58		
	1 6" 90° Transite Elbow		5 40		
	2 11½" Transite Elbow @ 2.24		4 48		
	3 Hrs. Town Shovel @ 6.50		19 50		
	3 Hrs. Trucking @ 3.00		9 00		
	1 Hr. Loader @ 3.00		3 00		
			195 99		

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS

SEWER DIVISION

Sketch of Service Here

A large rectangular grid of graph paper, consisting of 20 columns and 20 rows of small squares, intended for sketching service details.

Connection made in Street. Work completed

Remarks:
.....
.....