

Name **Walnut Const. Company**

Service No.

Address **30 Fuller ^{Road} Ave.**

Lexington, Mass.

Location

Kind of Pipe

Size

Size of Main

~~Repair~~ ~~Renewal~~ **New Service**

Location

Date	Material	Amount	Total	Date	Amount
Sept. 16, '48	Labor	53 52	53 52	Sept 7. 48	175 00
	10% Overhead		5 35	Dec. 31 48	38 45
	74'-6" Sewer Pipe @ .26		19 24		141 55
	1-6" Elbow		1 50	7-6-55	
	Joint Compound		4 44	Plumber Has been Here	
	5 hrs. Littlefield Shovel		35 00	2 Times July 6 + a week	
	2 hrs. D4 Tractor		6 00	before. Sand seems to be	
	2 hrs. Trucking		1 50	in pipe	
	Patching 15 x 3		15 00		
			141 55		
	Labor				

