

Name John Bullock Realty Const.

Service No. 161

Address 16 Garfield Street

Location

Kind of Pipe

Size

Size of Main

~~REPAIR EXISTING~~ New Service

Location *Caman 11-9-59*

Date	Material	Amount	Total	Date		Amount
8-17-59	Labor	79.78		8-13-59	<i>Deposit</i>	150.00
	10% O.H.	7.98	87.76	11-9-59	<i>Paid by SHC # 87</i>	10.91
	62' 6" Transite pipe @.70		43.40			160.91
	2' 6" Clay Pipe @.435		.87			
	1 6" Clay Elbow		1.88			
	3 hrs. Town Shovel @6.50		19.50	1-12-60	<i>Roots 60' ??</i>	
	2 hrs. Trucking @.75		1.50		<i>Respond + MEASURE</i>	
	1 hr. Trucking @3.00		3.00			
	1 hr. Rodgers Trailer @3.00		3.00			
			160.91			

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**  
**SEWER DIVISION**

Sketch of Service Here

A large grid of graph paper, consisting of 20 columns and 20 rows, intended for sketching service details.

Connection made in ..... Street.      Work completed .....

Remarks: .....  
.....  
.....