

Name **Carmela M. Ciampa**

Service No. **10**

Address **106 Gleason Road**

Location

Kind of Pipe

Size

Size of Main

~~Renewal~~ ~~Main~~ ~~Service~~ **W.O. #6180 & W.O. #6181**

Location **MAY 22 1978**

Date	Material	Amount	Total	Date		Amount
4/12/78	Labor	127.46		4-11-78	Deposit	300.00
	10% O.H.	12.74	140.18	5-22-78	Refund	88.82
25'	6" Transite pipe @1.50		37.50			211.18
1	4" Donut		3.55		OUTSIDE	
2	yds. Loam @4.50		9.00	4/11/ & 12	Labor	
5	lbs. Seed @.39		1.95	18'	6" Transite pipe	
2	hrs. Trucking @3.00		6.00	1	6" Elbow	
2	hrs. Backhoe @6.50		13.00	1	6" x 6" Nipple	
			211.18	1/2	Bag Cement	
					Patch	
				1	hr. Trucking	
				1	hr. Town Shovel	

DATE \_\_\_\_\_

**TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS**  
**SEWER DIVISION**

Sketch of Service Here

A large grid of graph paper, approximately 20 columns wide and 25 rows high, intended for sketching service details.

Connection made in ..... Street. Work completed .....

Remarks: *Original Service... 11-2-48* .....

.....  
.....