

Name

Service No.

Address

113 Gleason Rd

Location

Lexington MA

Kind of Pipe

Size

Size of Main

Repair—Renewal—New Service

Location

Date	Material	Amount	Total	Date	Amount
11-16-48	Labor				
	10% Overhead				
	60' 6" Sewer Pipe				
	Joint Compound				
	4 1/2 hrs. Littlefield shovel				
	1 hr. tractor				
	2 hrs. tuckering				

DATE _____

TOWN OF LEXINGTON — BOARD OF PUBLIC WORKS
SEWER DIVISION

Sketch of Service Here

A large rectangular area filled with a grid of small squares, intended for drawing a sketch of sewer service details.

Connection made in Street. Work completed

Remarks:

.....